Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: TI-STENBAK-158-95- 2526H-1

Field Name: TIOGA Well File #: 20070

Date Incident:5/4/2015Time Incident:21:00Facility ID Number:County:WILLIAMSTwp:158Rng:95Sec:25Qtr:

Location Description:

Submitted By: Jason Henry Received By:

Contact Person: Henry Jason

3015 16th Street SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:0.3 MileDistance Nearest Water Well:0.3 Mile

Type of Incident: Fire

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/13/2016 Clean Up Concluded: 5/4/2015

Risk Evaluation:

The fire was extinguished by personnel from the Tioga Fire Department. No injuries or evacuations occurred as a result of this incident.

Areal Extent:

Approximately 3 - 4 acres of burned pasture land and stubble field.

Potential Environmental Impacts:

There was no evidence of any fluid having been discharged from the flare.

Action Taken or Planned:

If any areas of impacted soil are observed in the burned area, that soil will be excavated and sent offsite for proper disposal.

Wastes Disposal Location: There are no waste streams to be disposed of following the fire. If any

areas of impacted soil are observed in the burned area, that soil will be

excavated and sent off-site for proper disposal.

Agencies Involved: Local Fire Department

Updates

Date: 5/7/2015 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 5/7/2015 at 12:36 p.m. Fire impacted stubble field to the north of well pad. Fire burned stubble in an area approximately 400 x 80 yards. There does not appear to be any liquids remaining related to the fire. No followup required.

Date: 5/7/2015 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.